

Reflective Cracking Testing Notes

Date: February 17, 2015

Project: Reflective Cracking Indoor Phase IV

Weather:

	6:54 AM	3:54 PM
Temperature (°F):	14.0	27.0
Dew Point (°F):	10.0	17.1
Humidity (%):	84	66
Visibility (Miles):	4.0	10.0
Wind (MPH):	9.2 NNW	9.2 NNW
Conditions:	Light Snow	Overcast

Working Hours: 7:00 AM – 4:30 PM

Sub-Contractor(s): None

Personnel: SRA

Equipment: Hand tools

Reflective Cracking Testing Notes:

The 12 mil formal test continued on the test item. The chiller remains inoperative due to a low flow fault.